

4E

Class is subject to the main engine crankshaft centre coupling Periphery cracks being specially examined before the end of July, 1961 (12 months limit), also to all electric wiring between the poop and midships accommodation being specially examined and repaired or renewed as found necessary by the end of March, 1961 (2 months limit).

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

19 APR 1961

SHIP'S NAME..... BRITISH PATIENCE..... REPORT Fre. No. 2463.....

SRL Item: Some temporary repairs effected to electric wiring between the poop and midship accommodation and on completion of the repairs all stern circuits Megger tested with good results.

IT IS SUBMITTED that this vessel is eligible to remain as classed subject as above with amended subject regarding electric wiring to be dealt with at the next drydocking.

G.V.P.

18.4.61.



© 2020

Lloyd's Register
Foundation

002550-002558-0098