

Received from Chief Ship Surveyor

6 AUG 1959

SHIP'S NAME

"BARON CAWDOR"

REPORT

Cff.

No. 60899

Outstanding Conditions of Class:

SUBJECT to deck plating in way of side bunker hatch (s.s.) being dealt with as necessary and to deck plating after end of forecastle (s.s.) and structure in way being specially examined and dealt with by the Special Survey, also to No.3 plate 2nd below sheer (s.s.a) and wasted shell plate G.5 (s.s.a) (doubled 9,58) being specially examined and dealt with as necessary by next drydocking.

S.R.L. — Appendix. (~~As before~~ or None)

Nature of Present Survey: (~~Afloat and~~ in dry dock)

Docking: Wear and tear repairs.

Recommendation:

SUBMITTED record of 'DS 7,59' be assigned, subject to deck plating in way of side bunker hatch (s.s.), after end of forecastle deck (s.s.), wasted side shell plates F.4, G.3 & 5 (s.s.a) and F.4 (p.s.f) being examined and dealt with as necessary by the Special Survey.

DS 7,59 Subject
Amended.

NOTE:- The Owners state that they may request postponement of the S.S.due 1,60 and the Surveyors recommend that any such request should be favourably considered and the present docking be credited towards a General Examination.