

"BRITISH EMPRESS"

- Lth. Rpt.No.24994.

The class is subject to indented shell plates D.1, F.1, G.1,2,3,4 & 5, H.1,2,3 & 4, (p.s.) and D.1, F.1 & 2, G.1,2,4 & 5, H.1,2,3,4,5 & 6 J.2,4,10 & 12, K.9 & 10 (s.s.) also to soft nose stem plate being specially examined and dealt with as necessary next Special Survey.

ACTION is DEFERRED for examination in dry dock after grounding.

There is a S.R.L.Appendix Note.

The ship was laid up and the Notation "Laid Up Surveys Overdue 12,59" assigned 20.1.61 on expiry of the year of grace.

The LEITH Surveyors in a report dated 12.7.61 state that a General Examination has been held with a view to towing the ship to a Firth of Forth port from Methil for breaking up.

The case has been transmitted to London.

IT IS SUBMITTED ACTION be DEFERRED pending receipt of further information.

IN S.R.L. APPENDIX.

Indents in a few shell plates (p & s).

IN S.R.L.

Drydocking(grounding).



©

2020  
11/8/61

Lloyd's Register  
Foundation

00299-002967-0094