

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

BERYL

Report

9B.

No.

61451

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

Damage, & 2nd S.S. No. 1.

When due

1, 40.

Subject to No 1 plate 2nd below sheer (p.s) see repair 4, 38
being specially examined at next dry docking.

a.f.

J.H.D.

© 17.8.39

The Certificate of Classification to
be endorsed "Cargo battens not
fitted" and the same notation to be
printed in the Register Book.

Lloyd's Register
Foundation

002568-002576-0096