

Port of IRVINE25th July 1939.

REPORT ON MASTS, SPARS, AND RIGGING.

Sir

Having, in accordance with your instructions,
examined the Masts, Spars, Iron Work of same, and Rigging, of the

Name of Vessel) S.S. "Beryl" of Glasgow

on the (Date of examination) 25th July 1939,

I have to report that I found Foremast.

By tapping with hammer and pricking with
pricker to be in bad condition, and condemned it.
Shrouds & stays in good condition.

Fore stay tightening screw in good condition.

Shroud tightening screws all in bad condition, and all
condemned.

Main Mast:- by tapping with hammer and pricking with
pricker to be, in good condition. All shrouds, stays,
and tightening screws to be in good condition.

Mizen Mast:- by tapping with hammer and pricking with pricker
to be in good condition. All shrouds, stays, and screws in
good condition.

Fee £ 10/-

To the Surveyors,

Lloyd's Register of Shipping,

George Leask

Foreman Carpenter

Will repair canvas
net 1/6/39