

3m. 2. 21.

1

Now Glenapp Castle x

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

EX "Gem"

Report

Gls.

No. 4390

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report 24/6/92.)

Name of Survey

1st Entry

When due

Revised Rules

+ 100A1 (Steel)

1 DK (pt. 5th)

'Well deck'

Cell D.B. f 105' 14 1/2. F.P.T. 34 1/2. A.P.T. 9 1/2.

F.K. 3 B.H. Rem. Lloyds A.K.P. Q 101' B 11' F 27' "Machinery aft."



© 2020

Lloyd's Register Foundation

28.8.24

002592-007601-0058

BEAMS, Poop Deck, Angle, Bulb Angle, Plate, Tee Bulb, or Channel

Angles on upper edge

Angle on ditto