

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name S.S. "FULHAM IV" Official No. 167157

Port of Registry LONDON

This ship has been under survey at SUNDERLAND

on OCTOBER 1955 and the following alterations to the conditions of

assignment of loadlines have now been ~~reported~~/found:—

ALTERATION.

Air pipes now found to be closed by wood plugs secured by chains. No wire gauzes or snifting holes are fitted.

SURVEYOR TO LLOYD'S REGISTER OF SHIPPING.

SUNDERLAND.

1st. NOVEMBER, 1955.

Guard stanchions with rails on Forecastle deck have been replaced by hinged guard stanchions with chains. This alteration was effected at some date previous to the survey October 1955. (per Sunderland letter 4.11.55).

Notes DPP 16 NOV 1955

FORWARDED TO THE OWNERS WITH A REQUEST THAT THIS BE

A copy of this Report has been placed on board.