

Engineer Surveyor

Received from Chief Engineer Surveyor

21 JUN 1957 4E

"FOREMOST 17".

REPORT

Sou.

No 24215.


Orders of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points stated in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH

MBS due 6.57, partly held now.

It is stated that the vessel is still laid up and that the shaft survey due 2.57, will be dealt with if the vessel goes into commission. In the circumstances it is submitted the RECORD of MBS 5.57, assigned, subject to the safety valves being adjusted and the oil piping arrangements examined before the vessel is placed in commission.



28.5.57.



© 2020

Lloyd's Register  
Foundation

007611-007619-0142