

14 SEP 1961

Received from Chief Ship Surveyor.....

SHIP'S NAME "FEDERAL VOYAGER" REPORT MTL. No. 14176

EA

Outstanding Conditions of Class: SUBJECT to set in shell plating etc. in way of No.1 hold (p & s) No.2 hold (p.s) and forward (p & s) also to set in shell plates JA 1, 2 & 3 (s.s.a) being examined and dealt with as necessary by the Special Survey.

S.R.L. Appendix. (AS ~~before~~ or None)

Surveys due: A SPECIAL SURVEY (C) became due 12,60 but postponement until 12,61 was approved 17.11.60.

Nature of Present Survey: (Afloat ~~and in dry dock~~)

Temporary repairs on account of contact damages (2).

Special Features:

It is stated the ship will be scrapped on her arrival in Japan, the Owners however, state they will advise us when she is delivered to the Breakers.

Is Interim Certificate in order (Yes ~~No~~ None)

Items Outstanding: (If any for S.S.)

S.S. to be completed by: 12,61.

Recommendation:

SUBJECT as above and to indented shell plating (p & s.f) being examined and dealt with as necessary before loading another cargo, but ACTION be DEFERRED for Special Survey and pending receipt of further information regarding breaking up.

SUBJECT.

WOT.  
14.9.61.