

COPY.

SUNDERLAND RPT. NO. 35611

SHORT BROS. LTD. YARD NO. 506

"CALLISTO"

Condition of vessel on the 24th July, 1950.


Further to the condition of the vessel as taken over from Mr. J.K. Young on the 14th April, 1950. The following structure now erected, scantlings checked, rivet pitch and welding examined and found satisfactory, sternframe erected, intercostal and floor at top to complete. Midship bottom shell riveted increases forward as approved. 90% of the tank top completed. All main and tween deck frames erected, bulkheads erected and partly riveted. Second deck beams, strongbeams and girders erected, scantlings checked and found satisfactory.

Signed _____

R. W. Wilson

Signed _____

H. Little



© 2020

Lloyd's Register
Foundation

002620-002630-0154