

SUNDERLAND RPT. No. 35611


"CALLISTO"

Short Bros., Ltd. Yard No. 506Condition of vessel, 14/4/50.

The following structure now erected, scantlings checked, rivet pitch and welding examined and found satisfactory.

Keel, centre girder, 75% of floors and 10% of tank top plating.

We agree that the condition of the vessel is as above.

Signed *James K. Young*Signed *R. Wilson*

© 2020
Lloyd's Register
Foundation

002620-002630-0155

Third

abaft $\frac{1}{4}$ len. from stem.....
Gussets, spacing and scantling.....