

COPY. 30/3/31. P.K.

For the information of Surveyors and the Committee only.

Order No. S. 10482... 2.7.1930.

Skoda 76-05.1284.

Received at

Office

19

# Lloyd's Register of Shipping.

(Report on Vessel No. 19304 Port Grk.)

## No. 1591. SHIP ~~FORGINGS~~ OR CASTINGS.

I have to report that the undermentioned ~~XXXXXX~~ Steel ~~Forgings~~ Castings, manufactured by The Limited Co., formerly Skoda Works of Pilsen, Czecho-Slovakia, for the Vessel No. 400, being built by Messrs. Robert Duncan & Co., Ltd. of Port-Glasgow, Scotland, have been inspected by me as set forth below and found to be, so far as can be seen, sound and free from defects. These have been despatched to Port-Glasgow.

on ~~XXXXXX~~ Castings.

Lloyd's

No. 508.

Prague, 29th September, 1930.

P.K. 26.9.30.

P. Kerlscher.

1-upper portion of 1-lower portion of

STERN FRAME.

~~BUDDER~~ FRAME.

~~XXXXXX~~

Open Hearth Steel

O A S T

Y E S

10 1/2" x 7 3/4", 9" x 7 3/4", to dwg. S.S. 400.

Rough machined

12th to 26th September, 1930.

CASTINGS.

Tests on Standard Test Pieces.

Tensile Test—

Tons per square inch

29.0 29.0 31.0 33.0

Elongation per cent. ...

27.6 35.5 27.6 32.9

Bending Test—

Angle before fracture

120 degrees

Test—

Height from ground ...

7 feet

Finishing Test—

Made according to Rules and found satisfactory ...

satisfactory

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.

LLOYD'S REGISTER  
GLASGOW

4- APR-1931

ANS 2020

Fee (if any chargeable) £

To be paid at PRAGUE.

\* If of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

5m.3.29. T.

002630-002638-0138