

COPY

# LLOYD'S REGISTER OF SHIPPING



Port St. John's, Newfoundland

10th March, 1961.

This is to Certify that ~~it~~<sup>we</sup> have

Surveyed the Machinery of the Single Screw Steamer "DASHWOOD", 2156 tons gross register of London (British) whilst lying afloat at this port on the 26th January, 1961, and subsequent dates,

~~we~~<sup>we</sup> and that ~~I~~<sup>we</sup> will transmit to the Committee of Lloyd's Register of Shipping, London, a Report stating that all recommendations made by ~~us~~<sup>us</sup> in connection therewith have been carried out to ~~my~~<sup>our</sup> satisfaction; also

that ~~I~~<sup>we</sup> will Recommend that in the case of this Vessel the following Survey Records be made in the Supplement to the Register Book (BS) Boiler Survey (date) and (ES) Engine Special Survey 2-61 on completion of the survey, and that her Machinery Classification Record be continued in the Book.

## Parts now examined:

(C.S. Items only)

### Main Engine

Cylinders, covers, pistons, rods, valves & gear; connecting rods, top ends and guides, crankpins & bearings. Main bearings and journals (crankshaft lifted). Thrust & bearings; holding down bolts and chocks, M.E. driven pumps, auxiliary condenser, Indepd. auxiliary feed; general service; 2 - oil unit; and main circulating pumps. Starboard generator & engine, forced draught fan engine, P and S main boilers.

*[Signature]*  
Engineer Surveyor to Lloyd's Register

#### KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(Cert. B.1.) 150m,5,60 (MADE AND PRINTED IN ENGLAND)

602647-002652-0009