

007647-007652-0134

MONTREAL OFFICE

Name:-

"HAMILDOC"

Report No. Mtl. 11737

Nature of Survey:-

DAMAGE

Damage stated caused by striking canal wall on the 16th August, 1957.

The following remains to complete the survey:-

Set in shell plating (port side forward) to be dealt with by next drydocking.

Recommendations:-

The Vessel appears eligible to remain as classed ^{with} ~~without~~ fresh record of Survey, subject as above.

Insert in S.R.L.

ALL 9/9/57

September 5th, 1957.

IN S.R.L. APPENDIX.

Indents in shell plates Nos. 1 in 2nd & 3rd below sheer (p.s.f) and