

29 MAR 19

Received from Chief Ship Surveyor

JD. SHIP'S NAME "DALEGARTH FORCE" REPORT Lon. No.

Outstanding Conditions of Class: NONEEndorsement of Class (B) (As before on ~~XXXXXX~~)Nature of Present Survey: (Afloat on ~~XXXXXXXXXXXX~~)


Temporary repairs effected to side shell leakage (s.s.).

Recommendation:

SUBMITTED the ship is eligible to remain as classed, SUBJECT to side shell plating in way of stokehold (s.s.) (leakage) being permanently repaired by next drydocking, and with Endorsement of Class (B).

As Now. Subject.

ENDORSEMENT OF CLASS(B).
Indented No. 4 keel plate and
shell plate A.5 (s.s.a.).



© 2020

Lloyd's Register
Foundation