

how 'Daleasth Force' "

Chief Surveyors 5. 4. 18

Received from Chief Surveyors

L'S NAME Steel SS. Crosteth

Report SL

No. 37610

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

of Survey When due

The chain cables are in accordance with the modified rules & the class should be without special conditions.

✱ 100 A.1. (Steel)

1 DR (Steel) Well DR

Cell DB + 114' 1716 F.P.T 606. A.P.T. 386

FK. 3BH. Cam. Lengths are. Q 109 B 13' F 26'

Truly aft.

M
5-4-18

It is concluded the ¹⁸ breadth of the sheerstrake buttships is as in the sister vessel, but the Surveyors should state if this is so.

M



© 2020

Lloyd's Register Foundation

00653-00658-0016