

Ship Surveyor.....

Received from Chief Ship Surveyor.....

12 JAN 1961

ME "FLEXITY" REPORT Lon. No. 144022

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

A SPECIAL SURVEY (C) became due 8,59.

The ship was last seen in dry dock in 3,59.

In reply to an enquiry the London Surveyors stated in a letter dated 21.10.59 that the ship was laid up at Greenhithe.

A report of a survey carried out by the LONDON Surveyors in 6,60 has now been received from which it is seen the ship was placed on slipway, the Special Survey commenced and recommendations for various repairs made.

It appears from the report that the machinery will be removed and the hull disposed of as scrap, but in a memo<sup>x</sup> the London Surveyors state the ship is laid up and the Surveys will be completed before she proceeds to sea.

IT IS SUBMITTED record of 'DS 6,60' be assigned.

IT IS ALSO SUBMITTED, pending further information, ACTION be DEFERRED and the Notation


"Laid Up, Surveys Overdue 8,59' be inserted in the Register Book.

DS 6,60.

INSERT IN R.B.

"Laid Up, Surveys Overdue 8,59"

W.S.I.  
11/1/61.



© 2020

Lloyd's Register  
Foundation

002659-002666-0046