

THE SURVEYORS ARE REQUESTED NOT TO WRITE IN THESE SPACES

Has screw shaft now been drawn and examined? *No* Is it fitted with continuous liner? ☒
Has shaft now been changed? ☒ If so, state reasons
Is the shaft now fitted new? ☒ Has it a continuous liner? ☒ Is an approved appliance fitted at the after ☒ efficiently lubr


S. S. Aldecron

Bel 2148.

Submitted that before dealing with this case
the surveyor should be requested to state whether
self closing cocks or valves have been fitted to the flat
guage glasses or the settling tanks or other suitable
means for ascertaining the level of the oil in these
tanks provided.

S.S.
10/1/23.

Bel: - 12/1/23
S. S. Aldecron



© 2020

Lloyd's Register
Foundation

002659-002666-0264

140 lb., E.D., &c.)

as far as how near it is in an efficient condition and
the condition of the engine as classed without fresh use