

1st September, 1959.

MONTREAL

12713, 815, 16, 32, 53, 87, 90, 92, 93, 902,
04, 05, 07, 24, 51, 64, 69, 70 - As recommended.

RMC 12965, 73, 78 - As recommended.

12908 "SIR THOMAS SHAHMEESY" - As recommended. I shall be glad if you will ascertain from the Owners and let me know what early arrangements can now be made for the electrical equipment to be examined for completion of the Engine Survey.

12885 "SILVAPALIA" - As recommended, except that the class has been continued subject also as previously recorded.

12891 "REDFERN" - As recommended. I shall be glad if you will request the Owners to state what arrangements they propose to make for the Special Survey to be held.

12894 "WILLIAM C. WARREN" - As recommended. I shall be glad if you will ascertain from the Owners and let me know what arrangements they propose to make to complete the Engine survey.

12897 "TORSHOLM" - As recommended. I shall be glad to learn why the donkey boiler safety valves were adjusted to 50 lbs.sq/in, bearing in mind that their designed working pressure is 105 lbs.sq/in.

12903 "J.S. WALTON" - As recommended. Please ascertain from the Owners and let me know what early arrangements they now propose to make for completion of the Engine Survey. No action per AH (c/b)

12947 "PRINS WILLIAM VAN ORANJE" - As recommended, except that the class has been continued subject as previously recorded.

© 2020



Lloyd's Register
Foundation