

Received from Chief Ship Surveyor.....

110 JAN 1962

SHIP NAME "APJ USHA" REPORT Bom. No. 15126

Outstanding Conditions of Class: SUBJECT to indented shell plates etc.
abreast E.R.(p.s.) being examined and dealt with as necessary
by the Special Survey.

R.L. Appendix. (As before ~~or None~~)

ture of Present Survey: (Afloat and in dry dock)

Equipment - 2 bower anchors and 5 fathoms of chain cable lost.

commendation:


SUBJECT as above, and to 2 bower anchors
being supplied at the earliest opportunity
but ACTION be DEFERRED for Equipment.

SUBJECT

IN S.R.L. APPENDIX.

Indented side and bottom shell plating (p & s).
Tunnel side plating in Nos. 4 & 5 holds indented.

W.V.I.
9.1.62.



Lloyd's Register
Foundation