

TELEPHONE. SUNDELAND 4093 (2 LINES).

All communications to be addressed to
THE SURVEYORS

Reference

D.O.

Lloyd's Register of Shipping.

55, Fawcett Street,

Sunderland, 19th January, 1945.

Dear Sir,

S.S. "EMPIRE MANDALAY".

In reply to your letter of the 16th instant, the
varnished cambric cables are sealed at the ends with waterproof
insulating tape. The maximum currents omitted from the Report columns are :-


"For'd Accommodation S.B.	-	-	amps	-	-	-
"Engineers Midship S.B.	-	-	52	-	-	"
"Crew aft S.B.	-	-	46	-	-	"
	1	7/.052	13	37	396	W.E. H.G.S.

Welded"

With regard to the seams and butts of the upper deck
plating at the fore and after ends, we have to confirm that they
are not electrically welded as in the sister vessels.

We are, Dear Sir,
Yours faithfully,
THE SURVEYORS,
PER:

The Secretary,
WOKINGHAM.



© 2021

Lloyd's Register
Foundation

000682-002689-0155

L.C.D.

DO
R.D.

22 JAN 1945

J.R.



© 2021

Lloyd's Register
Foundation