

ved by Chief Ship Surveyor

Received from Chief Ship Surveyor

SEL'S NAME

"DILOMA"

Rpt.

Liv.

No.

112620

he remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

It is submitted before this case receives the consideration of the Committee, the Surveyors should be informed it is concluded the riveting of the butts of side plating^{AMIDSHIPS} is quadruple and ^{THE}sheerstrake in way of bridge amidships quintuple, as indicated on the riveting scheme, and that the diameter of rivets in the butts of strake below sheerstrake amidships is 1" and not as reported, but this should be confirmed.

See letter
Lw. 12/6/39



© 2021

Lloyd's Register
Foundation

J. J. J.
W. J.
9.6.39