

Ship Surveyor

Steel S. S. "Humphrey"

Received from Chief Ship Surveyor

Rpt. Hul.

No. 33772

Reports of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

Endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. —Extract from Sub-Committee's Report, 24/5/92.

First Entry.

Submitted the Hull Surveyors be informed that it is found on the Cradley Heath Proving House that ^{Anchor} Certificate nos. C 27985 were issued for ordinary anchors 6.0.26 and 6.1.0. & stock cable certificate No 11026 for 15 fms of $5/8$ " short link cable. Should be requested to verify the certificate numbers on the bowes chain cable and also the test of the bowes anchors as same is not in accordance with the Rule requirements for weight of anchors reported.

Lr. 19/10/22



© 2021

RKM

18/10/22

Lloyd's Register
Foundation

002690-002700-0415