

21 DEC 1961

NAME "BRITISH DUKE" REPORT Nwc. No. 118463

inding Conditions of Class: SUBJECT to set in No.11 sheerstrake plate and No.9 in 1st below (p.s.f) also to G.10,H.6,7,10,11 & 14 and J.7 & 14 (p.s.f) and F.11 (s.s.f) all being specially examined and dealt with as necessary and to fractured pump room aft bulkhead (p.s.) being dealt with as necessary, by the Special Survey.

Appendix. (As before ~~or None~~) ACTION is DEFERRED for Special Survey.

s due: SPECIAL SURVEY (D) due 6,61. Postponement until 10,61 approved 28.4.61. Further postponement until 6,62 approved 28.9.61 provided a G.E. is held.

of Present Survey: (~~XXXXXXXXXX~~ Afloat and in dry dock)

Docking: General Examination: Damage and wear and tear repairs.

1 Features:

erim Certificate in order (Yes-~~No-None~~)

Outstanding: (If any for S.S.)

ALL ITEMS.

to be completed by: See Committee Minute.

mendation:

SUBMITTED record of 'DS 11,61' be assigned, subject as above, and to set in side shell plating in way of Nos2 (p & s) and 5 (s.s.) cargo tanks being specially examined and dealt with as found necessary by the Special Survey but ACTION be DEFERRED for Special Survey.

DS 11,61 Subject

IN S.R.L. APPENDIX.

Shell plate No.6 in 1st below sheer (s.s.a) indented.

IT IS FURTHER SUBMITTED the Owners' request for postponement of the Special Survey until 6,62 merits the favourable consideration of the Committee.

Lloyd's Register Foundation

002725-002735-0164

Before this case receives consideration submitted
the Nwc. Surveyors be referred to our letter of 1st
November from which it will be noted that a Modified S.S.
was requested for a period of 12 months, also their Report
No. 118463 of a GE.

Their comments are requested and if survey warrants
Mod. S.S. a new Report 8 should be furnished.

JAA

22nd December, 1961.



© 2020

Lloyd's Register
Foundation