



"EMPIRE STRAIT" & "EMPIRE LIGHT"

The defects reported by the Ministry of Shipping Surveyors would appear to have been ~~mostly~~ brought about under circumstances not under the control of the Society's Surveyors, but it is submitted in the first instance the correspondence be forwarded to the West Hartlepool and Glasgow Surveyors for their comments.

No Report appears to have been received from the Durban Surveyor regarding the "EMPIRE LIGHT".


17th February, 1941. 



© 2020

Lloyd's Register
Foundation

002743-002749-0190