

RTADORES Y
ORTADORES

LEFONOS:

Y CIA., SUCS., S. A.
(CASA ESTABLECIDA EN 1824)
SUCURSAL VERACRUZ

AL DUES
Board of Underw.

16 APR 1959

Received from Chief Ship Surveyor

IP'S NAME "C H A" REPORT L.A. No. 3306

standing Conditions of Class:

Subject to (leaky) side shell
riveting in way of No. 3 tween deck (p.s.) and (fractured) side shell
plating in way of No. 4 hold (s.s.) being specially examined and
dealt with as necessary also to (fractured) shell plate G.2 (s.s.f)
(locally doubled 12,58) being examined and dealt with as necessary
next drydocking.

Improvement of Certificate (~~As before~~ or None)

Location of Present Survey: (Afloat ~~and in dry dock~~)

Repairs to side shell plating etc. on account of contact damage.

Recommendation: SUBJECT as above.

As Now. Subject

Blk(new)

Incl: 2.

Andres Castro
February 9th, 1959



© 2020

Lloyd's Register
Foundation

002750-002753-0049

Lloyd's Agent(s)

vey; for
record of