

Last Report: No. 45707  
To be filled in at Head Office.

Port

ROT

Particulars of Classification (which must be inserted p  
in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations  
and Repairs (if any) must be stated in detail, the parts examined and their condition being

SHIP'S CLASS

Machin

Received from Chief Ship Surveyor

126 JAN 1959

SHIP'S NAME "C H A"

REPORT Rot. No. 46620

GB

Outstanding Conditions of Class: Subject to (leaky) side shell riveting  
in way of No.3 tween deck (p.s.) and (fractured) side shell plating  
in way of No.4 hold (s.s.) being specially examined and dealt with  
as necessary next drydocking.

Endorsement of Certificate (~~As before~~ or None)

Nature of Present Survey: (~~At float~~ and in dry dock)

Drydocking: Temporary and deferred repairs to fractured shell plate  
on account of contact damage: Wear and tear repairs.

Recommendation:

SUBMITTED record of 'DS 12,58' be assigned  
as recommended, subject as above,  
and to (fractured) shell plate G.2 (s.s.f.)  
(locally doubled 12,58) being examined and dealt  
with as necessary next drydocking.

DS 12,58 Subject

Blk(new)


Renewed .....  
Removed and Faired or Repaired .....  
Faired or Repaired in place .....

Has a Survey also been held on machinery of the Ship?

yes

Is Classification Certificate required? If so, to be sent to

not required



© 2020

Lloyd's Register  
Foundation

Doubling  
way of she