

MONTREAL OFFICE

e:-

J. G. IRWIN

Report No. Mt1. 12680

re of Survey:-

PART BOILER SURVEY

following remains to complete the survey:-



Repairs, as detailed in the Report, to

carried out.

The Owners' representative stated the repairs would not be carried out at this
as the vessel was to proceed to Port Colborne to be laid up for an indefinite time.
mmendations:-

~~The Vessel appears eligible to remain as classed~~ with ~~fresh record of~~
~~without~~

It is submitted action be deferred.



© 2020
Lloyd's Register
Foundation
June 8th, 1959

001754-001761-0642