

Dimensions:- 240 x 40 x 15 to Upper Deck
22.76 to Bridge Deck

1m, 10.43.

2

100A- (Classification contemplated)

LAST REPORT No. 9579 PORT L.A.

Sent to Chief Surveyors.....

Received from Chief Surveyors.....

VESSEL'S NAME S.S. "EL LIBERTADOR" REPORT Mob. No. 2077

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

No. 3 SURVEY PARTLY HELD. for Classification,
Damages & Repairs.

~~When da~~ (Vessel 15 years old) ~~When proposed to be completed~~ "EXAMINED hm. 5.44" 12 mos.

~~Part of~~ Survey held, &c. except repairs as below.....

TO COMPLETE THE S.S.:- Renewal of a number of deck plates on after main deck.

Subject to deeply indented shell plating etc. (p & s) being dealt with at the first opportunity.

(Docking date
5.44 Mob.)

"Examined hm. 5.44"

S.S. PART HELD
F.E. RPT. COMPLETED.

Lloyd's Register
Foundation

002762-002769-0010