

Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

S NAME "SPARKLER" REPORT Bel. No. 14460

ks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*

This Tug holds the notation of "Examined 9.46" valid for 12 months.

For conditions of class see previous endorsement.

The BELFAST Surveyors report 10.47 the vessel placed in dry dock, bottom coated and a GENERAL EXAMINATION carried out.

The damaged stem and stem plating, as above, examined and continues efficient.

It is submitted the vessel is worthy to remain as classed with record of docking survey 10.47 subject to permanent repairs to set over stem and stem plating at the first opportunity and to have the notation of "Examined 10.47" valid for 12 months assigned as recommended.

10.47 Ldy. subject.

Examined 10.47.



© 2020

Lloyd's Register
Foundation

002770-002783-0007