

RECEIVED

9.18 Recd 4.20

11 2 FEB 1960

Ans 12/21

12 FEB 1960

COMMITTEE LDN  
WL52 GDANSK 31/30 12 1545 NORTHERN  
= COMMITTEE LONDON TELEX  
= ~~HILDEGAARD E E E~~  
= HILDEGAARD NO 14358 IN RB STOP ER DAMAGED BY FIRE STOP  
FORWARD PLANS OF SWITCHBOARD AND ELECTRICAL WIRING FURTHER IS  
BOILER SURVEY DUE NOW STOP URGENT = REGISTER ++

14358 ++

SENT 1615 KD+

COMMITTEE LDN  
READ TIME SENT 1619 PSE PAL +

clear.



© 2020

Lloyd's Register  
Foundation

002770-002783-0085

CLASSIFICATION

H  
Reps

RU  
Reps advised

URGENT!



© 2020

Lloyd's Register  
Foundation

GENERAL  
S1a  
Has a Surety  
If so, is the  
EXAMINAT  
his service  
In damage ca  
Give dates an  
Cables are re  
Plating is dril  
from Repairs  
Repairs on acc  
should be sum  
amplified if ne  
Examination  
and Repairs (c  
clearly indica  
Surveys must