

Im, 12, 20.

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME Steel S.S. "SUNOCO"Report PHNo. 4081**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey _____

When due _____

✠ 100.A.1. (Steel) "Carrying Petroleum in Bulk"

2 Dks (Steel) & Web frames. "longitudinal framing"

Cell IB & E & B 60' 25gt, FPT 222t, APT. 57t.


F.K. 17 BH (13 BH to Upper Dk, 4 BH to 2nd Dk), pt Cam, A & CP, P133' B36' F 40'

Truly aft

See letter
21.4.21

It is concluded the pumping arrangements are similar to those approved for Sister Vessels but the Surveyors should be requested to state if this is so

6/4/21



© 2020

PH

7.2.21

Lloyd's Register
Foundation

002770-002783-0243