

"DESMOULEA" (Tanker built 12.1929)

Riveted. Combination Framing

This tanker was drilled in 10.56 and is not due to be drilled again until 10.64. However, at the request of the Owners, drillings as indicated on plan No. R/1443 were verified by the surveyors in connection with Singapore Report No. B.686.

IT IS SUBMITTED the Shell Petroleum Co. be informed that an examination of the upper deck and shell plating over the cargo tank length, as shown on Singapore Harbour Board's Drawing No. R/1443, indicates that renewals will be necessary at the Special Survey in 10.61 and that these have been indicated in red on the above drawing for their guidance, it being assumed that the drillings are representative of the general condition of the plating. Recommendations for renewal of plating outside the cargo tank length, and any amendments to the renewals indicated at present, that may be necessary, will be made by the Society's Surveyors at the time of the survey. 10.60

Copy of letter to Singapore Surveyors who should be requested to send an additional copy of the plan for eventual transmission to the Surveyors when the special survey is commenced.

alb. *Shin*
14th March, 1960

SS due 10.60
not 10.61

J.W.
O.H. Clemmette
requests his client
be amended accordingly.

© 2020



Lloyd's Register
Foundation

002784-002789-0101