

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

SHIP'S NAME "FIXITY" REPORT LON No. 144092

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/82.*)


This ship was built in 1944.

A SPECIAL SURVEY (C) becomes due 12,61.
She was last examined in dry dock 6,58.

The LONDON Surveyors report the ship examined on the slipway and renewal of 4 keel plates and the complete lower chine plates recommended.

It would appear now that this ship has been towed to Messrs. T. Ward Ltd., Thurrock, to be broken up for scrap metal.

In view of the above it is submitted
ACTION be DEFERRED pending further
information.



© 2020

Lloyd's Register
Foundation

002790-002797-0031