

3 MAR 59

Received from Chief Ship Surveyor

NAME

"JOHN HOPKINSON"

REPORT

Lon.

No.

139739

Standing Conditions of Class:

Subject to indented sheerstrake
Nos. 2 & 3, 1st strake below Nos. 3 & 4, and 2nd strake below
No. 3 and framing in way (p.s. from fwd.) being specially examined
and dealt with as necessary by the Special Survey.

Assessment of Certificate (~~As before~~ None)

Area of Present Survey: (Afloat ~~and in dry dock~~)

Temporary repairs on account of contact damage.

Recommendation:

SUBJECT as above, and to stem and stem plating
being specially examined and dealt with
as found necessary by the Special Survey,

As Now. Subject



© 2020

June
3/2/59

Lloyd's Register
Foundation