


Do. 5, Denman St., London Bridge, S.E. ... Hop 5958
 Do. 10, Creechwich Lane, E.C.3 ... Avenue 6271 [2 lines]
 Do. 4, Holborn Viaduct, E.C.1. ... City 4809
 Do. 1, Northumberland Av., W.C.2. ... German 51
 Do. 100, Piccadilly, W.1 ... Central 6012 [2 lines]



CASTLE-ON-TYNE : 29, Sandhill ... Central 1356 [2 lines]
 BIRMINGHAM : 95, Colmore Row ... Central 2084 [3 lines]
 BRISTOL : Back Hall Chambers, Baldwin Street ... 2555 [2 lines]
 WESTON-SUPER-MARE : 3, Richmond Street ... 143
 GLASGOW : 105, Hope Street, C.2 ... Central 7509 [2 lines]
 EDINBURGH : 18a, Frederick Street ... 20384
 4504

INCHES IN

2m. 11.28.

1

John Augustus Eslinger

Sent to Chief Surveyors

Received from Chief Surveyors



VESSEL'S NAME *Stl Se M/V* "WESTERN SUN" Report *Shl* No. *6112*

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey *1st Entry* When due Revised Rule

✠ 100 A.I. (Steel). Carrying Petroleum in Bulk
 2 D¹⁰ (Stl) • Web Frames, Longitudinal framing, Bracketless Systems.
 Cell D.B. v E 76' + Ho' 4885, F.P.T. 186t, A.P.T. 84t.
 F.K, 17 B.H (13 B.H to upper D¹⁰, 4 B.H to 2nd D¹⁰) ft Com, Clayds ACP
 P 79', F 48'.
machy apr.



002798-002807-0019

No Inquiry respecting this Message can be attended to without the production of this paper. Repetitions of doubtful words should be obtained through the Company's Offices, and not by direct application to the Sender.

002798-002807-0020

OFFICE APPLIANCE CO., LONDON, W.B.1

Lat