

Surveyor to assure himself of the thorough efficiency of those parts of each Boiler: )  
State latest date of internal examination of each boiler: Port 11-11-57 Starboard 18-11-57 Present condition of fund  
Did the Surveyor examine the Safety Valves of the Main Boilers? Yes To what pressure were they afterwards adjusted under  
were they afterwards adjusted under

## MONTREAL OFFICE

Name:- "CITY OF TORONTO"

Report No. Mtl. 12101

Signature of Survey:- Pt.BS

The following remains to complete the survey:- Safety valves to be adjusted under steam.

NOTE:- This vessel laid up pending a decision whether she will be commissioned this Season.


### Recommendations:-

The Vessel appears eligible to remain as classed ~~without~~ with fresh record of MBS 1,58 when the survey is complete

Insert in S.R.L.

002798-002807-0099

Ma ~~Clare~~



© 2020

Lloyd's Register  
Foundation