

F.E.

ed by Chief Ship Surveyor \_\_\_\_\_

Received from Chief Ship Surveyor \_\_\_\_\_

Vessel's NAME Stl T.S. "ERRIA" Rpt. cpw. No. 8690

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 16390 Depth "d" ✓Framing: Table No. ✓ Description Bulb angle framesLongitudinal No. 43670Proportions  $\frac{\text{Length}}{\text{Depth}} = \frac{11.8}{1}$ ~~Deck~~ Sheerstrake as approved

Vessel placed on Pontoon.

Some damage sustained during launching repaired to Runby's satisfaction.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✠ 100 A.1. (Steel) "with freeboard," as recommended. Carrying Vegetable oil in deep tank forward. The Summer freeboard of 10ft - 0 $\frac{1}{2}$ in from centre of disc to top of statutory deck line at — deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, as shown on the accompanying verification form to be inserted in the certificate of classification.

2 D<sup>co</sup> (Stl) 3<sup>rd</sup> D<sup>c</sup> (Stl) in N<sup>o</sup> 1. 3 holds.

Cell D.B. 378' 1384t, tanks in way of tunnels, D.Ta 12' 280t, DTf 22' 556t, F.P.T. 80t, A.P.T. 100t

F.K. 8 B.H. (1 B.H. to 3<sup>rd</sup> D<sup>c</sup>) Lloyd's A.C.P.

P 31' B 210' F 70'.

002808-002815-0141

© 2020

Lloyd's Register  
Foundation

22.1.32