

" CABO TORINANA "

Shell drillings at end

C.C.3

51 (6 Lines)

2.

FORD.			AFT.		
ORIG.	P.	S.	ORIG.	P.	S.
-	-	-	-	-	-
.50 ✓	Cement		.50 ✓	Cement	
.50 ✓	-	-	.40 ✓	Cement	
.45 ✓	-	-	.40 ✓	.35	.35
.45 ✓	-	-	.45 ✓	.40	.34
.40 45	.52	.44	.45 ✓	.38	.38
.45 ✓	<u>.25</u>	<u>.26</u>	.40 ✓	.36	.40
.40 ✓	<u>.28</u>	<u>.28</u>	.40 ✓	.32	.38
.40 ✓	.40	.40	.40 ✓	.36	<u>.24</u>
.40 ✓	.44	.42	.40 ✓	<u>.25</u>	<u>.25</u>
.40 ✓	<u>.28</u>	.42	.40 ✓	<u>.25</u>	<u>.25</u>
.45 ✓	.44	.46	.45 ✓	<u>.30</u>	<u>.30</u>

Dim

p. 5.

5 5

5 11

7 7

4 -

8 2

4 R

R R

R R

R 15

lette
hedshi
seds
ed
hat

plates underlined are being renewed.

itt



© 2021

Lloyd's Register
Foundation

002816-002824-0157

including the examination and testing of the steam pipes