

6 NOV 1956

Received from Chief Ship Surveyor

SHIP'S NAME "LANDPRIDE" REPORT H.Kg. No. 13226

GB

Outstanding Conditions of Class: Subject to sternframe solepiece (E.W. & reinforced 1,54 & E.W. 4,51) being specially examined at next drydocking, also to the suction pipe (wasted) in No.3 D.B.tank being renewed on ship's return to U.K. from present voyage.

Endorsement of Class (B) (As before or None)

Surveys due: SPECIAL SURVEY (C) due 3,56. Postponement until 9,56 approved 4.4.56 as the result of a satisfactory General Examination held Brw. 3,56.

Nature of Present Survey: (Afloat and in dry dock)

Special Survey (C) largely held: Repairs effected to tank top plating and bottom shell plating, etc.  
This ship has been converted to oil fuel burning at this time in accordance with approved plans.

Special Features:

Is Interim Certificate in order (Yes-No-None)

Items Outstanding: (If any for S.S. or A.S.)  
TO COMPLETE THE S.S.:-- EXAMINATION of hatchway tarpaulins.

S.S. to be completed by: Owners state the Special Survey will be completed in a few weeks time.

Recommendation:

SUBMITTED record of docking 8,56 be assigned, without special conditions the Notation of 'ss.H.Kg. 8,56' being WITHHELD for completion of the Special Survey.

8,56 H.Kg. Without.

S.S.PART HELD.


DELETE 'ENDORSEMENT OF CLASS (B)'

INSERT IN R.B.  
O.F. 8,56.

INSERT IN R.B. (Vol.II)  
DB pt O.F. pt W.B.

DELETE FROM R.B. (Vol.II)  
1207t.

NOTED FOR POSTING



© 2021

Lloyd's Register  
Foundation

Blk(new)

002816-002824-0329

Special Damage or Repair Fee (if any)

21/8/1956



Surveyors advised of the condition of class -  
 Suction pump (was) in No. 1 D.B. tank being renewed on  
 ship's return U.K. from present voyage, and requested  
 to confirm that this work was done with during the Special  
 Survey

*Cancelled*  
*This item previously dealt with*  
*See letter dated 12.4.56*

IT IS FURTHER SUBMITTED the Hong Kong

N.  
 Last  
 Periodical  
 the Su  
 and su  
 other  
 replace  
 State a  
 In dama  
 he  
 REPAIR  
 REPA  
 Now  
 Exam  
 SUMMA  
 Re  
 Re  
 Fa  
 PRESEN  
 Decks  
 Caulking  
 Coaming  
 Beams &  
 Outside  
 Frames  
 Reverse  
 Longitud  
 Transve  
 Floors  
 Keelson  
 Stringer  
 Inner B  
 Have th  
 Have th  
 Gen  
 th  
 su  
 8, 5  
 exa  
 urvey  
 Special  
 Travelli  
 Second  
 Com



© 2021

Lloyd's Register  
 Foundation