

Rpt. 8

JWK:

Port of ROTTERDAM.

46009

Date of writing Report 8-9-1958.

When handed in at Local Office

Received London

12 SEP 1958

Survey held at Rotterdam

No. of Visits 3

First Date 27-8-1958

Last Date 28-8-1958

## REPORT OF SHIP SURVEYS AND REPAIRS

The Surveyor's attention is drawn to the relevant requirements of Chapters B & C of the Rules.)

No. in R.B.

61722

S.S.

on the ~~Steel~~ ~~MSX~~

"GALLIUM"

Tons gross

1775

Built at

Blyth

By Whom

Blyth S.B. & D.D. Co. Ltd.

When

Year 1924

Month 7

Owners

Société Navale Caennaise (Anct.G. Lamy & Cie)

Owners' address

(If not already in R.B.)

Managers

Port of Registry

Caen

Surveyed Afloat or in Drydock

afloat

Name of Dock

Date of last examn. in Drydock

N.B.—Any alterations in existing particulars in the Register Book should be reported and underlined.

Last Report: No.

1079

Port

RoU

To be filled in at Head Office.

Particulars of Classification (which must be inserted precisely as in Register Book and Supplement)

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of Examination and Condition on the back of the Report is to be carefully completed and amplified if necessary in the body of the Report. Outstanding items to complete the Survey should be summarised at the end of the Report. The reasons for Repairs must be stated. Repairs on account of Damage (the alleged cause of which must be stated) should be separated from Repairs due to other causes, and, besides being detailed in the body of the Report, should be summarised in the form below. When, at a Special Survey, the Shell and Deck Plating is drilled the results must be reported on Report 8(Dr). Whenever Anchors or Chain Cables are replaced or retested the necessary particulars are to be given on Report 8(Eq) which is to be attached to this Report.

Give dates and references to any letters relating to this Report

SHIP'S CLASS Date of Special and of Drydocking Surveys, etc.	Machinery
*100A1	* LMC 2-55
Dock 1-58	MBS 2-58
SS. (Dr.) 3-47	TS 1-58 CL
SS. Rou. 2-55	Sps 2-55

In damage cases where the Surveyor has not made a special damage report he should state whether he offered

his services for this purpose and to whom and why they were declined

Freeboard as marked on ship and now verified

ft

ins

Was a damage report made by anyone else? If so, by whom?

EXAMINATION AND REPAIRS AS PER RULE FOR SURVEY FOR REPAIRS.

Attended on board at request of Owners' Agents in order to examine steering leads. Vessel put back to port after reported rupture of a link in one of the steering chains.

Broken steering chain renewed (L.R. certified chain) and connected up.

Steering gear tried and found in order.

Steering leads examined and found or made in order.

CONTINUATION OVER/OR SHEET 2

SUMMARY OF DAMAGE REPAIRS	Shell Plates	Frames	R. Frames	Floors and Bracket Floors	Inner Bottom Plates	Deck Plates	Beams	Other Items
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

Has a Survey also been held on machinery of the Ship?

NO

Is Classification Certificate required? If so, to be sent to

If so, is the Report sent now, or when will it be sent?

--

Has Interim Certificate been issued? copy attached

GENERAL OBSERVATIONS, OPINION AND RECOMMENDATION AS TO CLASS

State clearly what alteration, if any, is suggested to be made in the existing Classification or Survey or other records of the Ship in the Register Book consequent upon this survey; for example:—"to remain as Classed in the Register Book without fresh record of Docking"; "to remain as Classed and to have record of drydocking 1,55"; or "to remain as Classed and to have record of drydocking 1,55, and the notation of S.S. . . . 1,55".

It is submitted this ship is eligible to remain as classed without fresh record of survey, subject to all conditions at present attached to the vessel's class being dealt with as previously recommended.

As now.  
is as before.  
J. J. J.  
23/9/58

Surveyor to Lloyd's Register of Shipping

H.Th.G. Steenstra.

Date of Committee

THURSDAY 25 SEP 1958

Minute

As now, subject.

Noted  
for  
Header

30m.4,57 T.

002825-002829-0188



PARTS OF THE SHIP AS INDICATED BELOW HAVE BEEN EXAMINED FOR.

## SURVEY.

Have the spaces now surveyed been cleared and cleaned as necessary? .....

Have the close ceiling and cargo battens, linings, pipe casings, etc., been removed and replaced as required by the Rules? .....

Have the bilges been cleaned out and examined? ..... Has cement in bottom been examined? .....

Has steelwork had rust removed and afterwards been recoated as necessary? .....

Were inspection plugs or any insulation removed in insulated spaces for examination of steelwork? .....

Has a Load Line Survey been held? ..... If so, state which ..... ..

Have the shell and deck plating been drilled as per Rule? ..... If so, Report 8(Dr) to be attached .....

Have any alterations to the approved scantlings and arrangements now been effected? ..... If so, report details in body of Report. ....

NOTE:—Indicate which compartments and/or tanks have been examined or tested by giving the identification numbers and inserting the word “Yes”, e.g. Holds: Nos. 1, 2 & 3—Yes; or All—Yes.

The present condition of the following parts in so far as examined is to be reported:—

Have conditions (A) or endorsements (B) of Class (if any) been dealt with? ..... no ..... See Below .....

REMARKS, REPAIRS, Etc. (Contd.)

Survey Fee ..... Fl. 120.-

Special Damage or Repair Fee (if any)

Travelling Expenses (if chargeable)..... Rs 11/-

*Second Surveyor's Fee (if any)*

Date when A/c. Rendered

© 2020

Lloyd's Register  
Foundation