

24 MAR 1960

Received from Chief Ship Surveyor.....

S NAME "DIMITRIOS A.KYDONIEFS" REPORT Sng. No. 13791  
SUBJECT to shell plate B.8 (fractured & doubled) (s.s.) being dealt with next dry docking, to shell plate A.8 (s.s.a) and fore  
standing Conditions of Class: mast being specially examined and dealt with as found necessary also to further examination of No.1 D.B.tank and repairs as necessary next S.S., to 15 fathoms of chain cable being supplied and to cargo battens being placed in order at the earliest opportunity, also to holed shell plate No.1 in 1st below sheer (ss) and shell plate in 1st strake above round of bilge in way of B.R. (p.s.) being permanently repaired by 1,60. ACTION is DEFERRED  
Appendix. (As before or None) for Special Survey by 5,60.  
Days due: SPECIAL SURVEY (C) due 5,59. Postponement until 5,60 approved 14.7.59. G.E. held 6,59.

Condition of Present Survey: (Afloat and in dry dock)

Examination of part deferred items as above.

Special Features:

Interim Certificate in order (Yes-~~No~~-None)xx

Outstanding: (If any for S.S.)

ALL ITEMS.

to be completed by: 5,60.

Recommendation:

SUBJECT to shell plate B.8 (fractured & doubled) (ss) being dealt with by next drydocking, to shell plate A.8 (s.s.a) and fore mast being specially examined and dealt with as found necessary, also to further examination of No.1 D.B.tank and repairs as necessary next S.S., to 15 fathoms of chain cable being supplied and to cargo battens being placed in order at the earliest opportunity, also to holed shell plate No.1 in 1st below sheer (s.s.) and shell plate in 1st strake above round of bilge in way of boiler room (ps) being permanently repaired by 3,60, but further ACTION continue to be DEFERRED for S.S. by 5,60.

SUBJECT  
AMENDED.

The Owners' Representative states that this ship after discharge at Tsamkong will proceed to Hong Kong for breaking up.

002846-002852-0212