

# COPY

## LLOYD'S REGISTER OF SHIPPING

2763



Port "JUI YUNG" YOKOHAMA

This Certificate Accompanies YOKOHAMA 3rd December, 1958

**REPORT** No. 2763

Dated 9-12-58


**This is to Certify** <sup>we</sup> ~~that~~ <sup>we</sup> ~~I~~ have  
 Part ~~Surveyed~~ the Machinery of the S.S. "JUI YUNG" 10928 tons gross of  
~~Keelung, whilst the vessel lay afloat and in dry dock at Yokohama and~~  
~~Tokyo on the 3rd December, 1958 and subsequently~~

<sup>we</sup> ~~and that~~ <sup>we</sup> ~~I~~ will transmit to the Committee of Lloyd's Register of  
 Shipping, London, a Report stating that all recommendations made by  
<sup>us</sup> ~~me~~ in connection therewith have been carried out to <sup>our</sup> ~~my~~ satisfaction; also  
<sup>we</sup> ~~that~~ <sup>we</sup> ~~I~~ will **Recommend** that in the case of this Vessel the following  
 Survey Records be made in the Supplement to the Register Book  
Main Boiler Survey (MBS) 12,58 on completion

~~and that her Machinery Classification Record be continued in the Book.~~  
~~and without subject regarding starboard main injection valve.~~

**Parts now examined:**  
~~(C.S. Items only)~~


To Complete MBS:- Forward Port, centre and starboard boilers to be examined  
 in their entirety.  
 Oil fuel burning installation and remote control gear to  
 be examined.

  
 Engineer Surveyor to Lloyd's Register.  
 H. TERASHIMA & K. MOCHIZUKI

**KEY TO ABBREVIATIONS**

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS (CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS (OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

<sup>/ft</sup>  
 This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-  
 "While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly  
 executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances  
 whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any  
 entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its  
 Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



002846-002852-0277