

State latest date of internal examination of each boiler.....15-10-57

Present condition of

Did the Surveyor examine the Safety Valves of the Main Boilers?.....Yes

To what, pressure were they afterwards adjusted

Did the Surveyor examine the Safety Valves of the Donkey Boilers?.....

To what pressure were they afterwards adjusted

Boilers?.....Yes..... and of the Donkey

MONTREAL OFF.

Name:- "CITY OF KINGSTON"

Nature of Survey:- Pt.BS

liner?.....Is an approved oil retaining applia

the shaft now fitted been previously used?

te date of examination of Screw Shaft.....

did the Surveyor examine the generators, motors, swi

not less than 100,000 ohms?

ry should be referred to by position in Machine

pains to be done.....

The following remains to complete the survey:- Safety valves to be adj^{ther} with principal mount

NOTE:- This vessel laid up pending a decision whether she will be team.
this Season.

sioned this season

Recommendations:-

The Vessel appears eligible to remain as classed ~~without~~ with fresh record of MBS 12,57 whe. placed in good
survey is comp

Insert in ✓ S.R.L.

002853-002857-0099

Lloyd's Register
Foundation
May 2nd, 1958

General Observations, Opinion, and Recommendation :-