

The class is subject to lighting and fan circuits in midship's accommodation being altered to conform with Rule requirements at the earliest opportunity.

4E

22 OCT 1957

by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

NAME.....ERINNA

REPORT.....Sng

No.12137

Repairs. CS Advanced.

IT IS SUBMITTED this vessel is eligible to remain as classed, subject as above.

[Handwritten signature]

18.10.57.

In view of the length of time which has elapsed since the above condition of class was imposed, and that the Owners have stated that the matter would be dealt with at the Special Survey, IT IS SUBMITTED they be asked what action is being taken.

(A fresh CS record was arranged 6.57)

✓ 5/11

© 2020

Lloyd's Register
Foundation

002858-002869-0008