

REPORT of SURVEY of REPAIRS, &c.

Date of writing Report When handed in at Local Office Port of LONDON

No. in Reg. Book. Supp. 41317 Survey held at on the Wood, Iron or Steel Date, First Survey 1905 Last Survey 10

TONNAGE - Built at Newcastle By whom Wood, Skinner & Co. When 1905

GROSS 2539 Owners Mimpanu Ss Boha WRECK SECTION Owners' Address WRECK SECTION

NUMBER DK. 2388 Managers WRECK SECTION Port belonging to Glasgow

NET 1616 Name of Dock No. 711 Destined Voyage

Surveyed Afloat or in Dry Dock? WB=CeUDBorDBa feet; uE&B feet; f feet

total capacity tons. FPT tons; APT tons; MT feet tons. Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 87882 Port Newc

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.)

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

CHARACTER. * for Special Survey Date of last Survey and of Periodical Surveys.	Years Assigned or Expired	Machinery and Boiler Surveys (including date of N.B., if any)
+100A 12.19		+Lmc 10.27
S.S. 26 No 3-5.19		BS 12.31
S.S. 26 No 2-27		TS 12.19
Cargo Ballers not fitted		NAB 24

Society's Freeboard (if assigned) as painted on Ship and now verified

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks	State if Tanks have been examined inside	Dblng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessel (State if on Felt). When put on, Month
Caulking of Decks	State if Tanks now tested	Engine Room Skylights	Boats
Coamings	Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Scuppers	Condition, how ascertained (State if wedges removed)
Outside Plating	Cement or Asphalt (State which.)	Cargo Hatchways	Sails
Breasthooks	Rudder	Hatches	Equipment letter
Transoms	Steering gear and its connections	Planking of Wood Vessels	Anchors, No. of
Frames	Windlass	Caulking ditto	Cables (State if now ranged)
Reverse Frames	Have Pumps now been examined and found efficient?	Treenails ditto	„ length (on board)
Longitudinals	Have Sluice Valves now been examined and found efficient?	Breasthooks & Stomson ditto	„ Rule length
Transverses	Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Hawser & Warps
Floors	Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	Standing and Running Rigging
Keelsons		Ditto Ditto at other places ditto	
Stringers		Stringers, Clamps & Shelves ditto	
Inner Bottom Plating		Salting (State if examined.) ditto	

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—“to remain as now classed in the Register Book without fresh record of Survey,” “to remain as classed and to have record of survey, 1,24,” or “to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and pND24, &c.”

Survey Fee (per Section 20)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 20)	£	:	:	19
Travelling Expenses (if chargeable)	£	:	:	Received by me.
Second Surveyor's Fee (if any)	£	:	:	19

Committee's Minute Expunge class TUE 14 JUN 1932 with Red Line

Character Assigned with Red Line

Surveyor to Lloyd's Register of Shipping: Special General Committee Thursday, 16th June

Classing Committee Register of Shipping decision confirmed