

Received from Chief Ship Surveyor

SHIP'S NAME

"THEOBALDIUS"

REPORT

Rot. No

Outstanding Conditions of Class: SUBJECT to indented side shell plating etc. in way of No.5 cargo tank (s.s.) being examined and dealt with as necessary by next Special Survey, to shell plate A.6 (p.s.f) being examined and dealt with as necessary and to stem and stern plating, stern plating etc. and bottom shell plating in 'A' strake in way of No.2 centre tank (p.s.) being specially examined and dealt with as found necessary by the next drydocking.

R.L. — Appendix. (As before ~~or None~~)

Nature of Present Survey: (Afloat and in dry dock)

Docking: Wear and tear repairs:
Examination of deferred items as above.

Recommendation:

SUBMITTED record of 'DS 7,59' be assigned, subject to indented side shell plating etc. in way of No.5 cargo tank (s.s.) and shell plate A.6 (p.s.f) being examined and dealt with as necessary ~~also~~ to stem and stern plating, stern plating etc. and keel and bottom shell plating in 'A' strake in way of No.2 centre tank (p.s.) being specially examined and dealt with as ~~found~~ necessary, ~~also~~ by the Special Survey.

DS 7,59 Subject
Amended.

IN S.R.L. APPENDIX.

Shell plating (s.s.f) indented.



© 2020

CS
4-9-59

Lloyd's Register
Foundation