

COPY

Newcastle

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

NEWCASTLE-ON-TYNE, No 108926



.9956.

Port MANCHESTER.

15th June, 1951.

This is to Certify that

R. C. CLAYTON,

the undersigned Surveyor to this Society did at the request of Messrs. Hamilton Woods Ltd., Salford attend at their Works on the 12th June, 1951 for the purpose of examining and testing the following valves made to the Order No. S.S.20654 of Messrs. Watts Pincham (1932) Ltd., 24 Tidal Basin Road, London E.C.16, and intended for despatch to Messrs. Smith's Dock Co. Ltd., North Shields to be marked for A.S.P. Co., "R" Class ship - Propane Scheme.

- 11 - 4" cast steel wedge type sluice valves, flanges A.S.A. class 300 with raised faces and with gunmetal glands and indicators.
- 4 - 4" gunmetal blank flanges to suit the above.

The cast steel bodies and domes for these valves have been made at an Approved Steel Works, and have been inspected and tested by a Surveyor to this Society.

On completion, the valves have been subjected to an oil pressure test of 600 lbs/sq.inch to ensure soundness of the castings and tightness of the valve. These tests were satisfactorily carried out and, as far as could be seen, the materials and workmanship employed have been good and sound.

For identification purposes the valves have been stamped Lloyd's Test 600 lbs/sq.inch R.C.C. 12.6.51.

R. Clayton

SURVEYOR TO LLOYD'S REGISTER OF SHIPPING.

Fee: £4/4/0d.

© 2020

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

“While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.”