

## REPORT OF SURVEY ON SHIPS CLASSED FOR GREAT LAKES AND ASSOCIATED SERVICES

Date of writing Report April 22nd, 1960. When handed in at Local Office 19 Port of MONTREAL  
 No. in Reg. Book 24885 Survey held at MONTREAL Date, First Survey and Last Survey April 21st, 1960.  
 (No. of Visits 1)

on the Steel " JAMES J. BUCKLER " ex Outarde  
 TONNAGE:— Built at Newcastle-on-Tyne By whom Palmers' Company Limited When 1924 8  
 GROSS 2241 Owners Quebec & Ontario Transportation Company Limited  
 UNDER DK. Managers  
 NET 1576 Port belonging to MONTREAL

Surveyed Afloat or in Dry Dock? Afloat Name of Dock Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

Last Report, No. 3746. Port TTO.

REPAIRS, OR EXAMINATION AS PER RULE FOR

LAKE ANNUAL SURVEY

NOTE: Surveyors must indicate clearly the items examined (a crow mark is not sufficient), the condition found and the repairs effected.

CHARACTER. + for Special Survey. Date of last Survey and of Periodical Surveys.	Machinery and Boiler Surveys (Including date of N.B., if any).
*100 A1 with fbd For service on the Great Lakes & Gulf of St. Lawrence with occasional voyages to Newfoundland and Sydney, Nova Scotia. Lake S.S. 12/56 A.S. 4/59 D.S. 12/56	*LMC ES 12/56 MBS 2/59 TS(C.L) 12/56 SPS 12/56

ITEMS EXAMINED AND CONDITION FOUND, ETC.			
Holds including bulkheads, inner bottom plating, etc.			Good
Bilges & ceiling.			-do-
Tween decks.			-do-
Deck & deck erections.			-do-
Machinery Space.			-do-
Under Engines & Boilers.			-do-
Masts, Rigging & Outfit.			-do-
Windlass & Hawse Pipes.			-do-
Air & Sounding Pipes with closing appliances.			-do-
Pumps and Pumping arrangements outside machinery space.			-do-
Steering arrangements including gear.			-do-
W.T. Doors & Sluice valves.			-do-
Ventilator coamings with their closing appliances.			-do-
Hatchway coamings with their closing appliances.			-do-
Casings, companionways and their closing appliances.			-do-
Superstructure bulkheads with their closing appliances.			-do-
Guard rails & freeing ports.			-do-
Overboard discharges, also ash chutes & other shell openings.			-do-
	EXAMINED	TESTED	CONDITION
Peaks	Yes	No	Good
Side Tanks in hold.			
Deep Tanks			
Cargo Tanks			
Cofferdams			
Pump Rooms			
(Tankers)			
Has a Load Line Annual Survey been held?	Yes		
Has a Grain Survey been held?	Yes		
Has a Damage Survey been held?	No		

## General Observations, Opinion as to Class, Recommendation, Etc.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of Annual Survey 4.54" or "to remain as classed and to have record of docking, I,54 and the notation Lake S.S. 4.54.

This ship is eligible to remain as classed with record of ANNUAL SURVEY 4,60

Survey Fee \$36.00  
 USSA 4.00  
 Special Damage or Repair Fee (if any) \$  
 Travelling Expenses \$ 5.00  
 Second Surveyor's Fee (if any) \$  
 Committee's Minute  
 Character Assigned AS 4.60  
 MBS 2.60

Fees applied for,  
 APR 29 1960

TUESDAY 24 MAY 1960

Surveyor to Lloyd's Register of Shipping.

( D. McKINNON )

Noted  
 for  
 Header

002891-002896-0007

© 2020  
 Lloyd's Register  
 Foundation