

Steamer "JEAN BAPTISTE" ex.

"ASSAMINA K"

This ship has been broken up
(Committee Minute dated
12th August, 1960).

Mr. Loukisas of Messrs. J. P. Hadoulis (Owners) has telephoned to say that the spare ^{tail} shaft was taken off this ship prior to breaking up and is now lying at Hamburg. It is their intention to sell this shaft but a test Certificate is required. The markings on the shaft are "Lloyd's KF 3857 18/5/51. There is, however, no trace of this Test Certificate in this Office, and Mr. Loukisas has been advised that it will be best if a further test was carried out with a view to a Certificate being issued. Furthermore he has been informed that a letter will be forwarded to him giving the requirements of the necessary test.

1. Obtain copy of test certificate from Sunderland.
2. Inform J.P. Hadoulis that a Brinell test could be carried out at Hamburg.
3. Inform J.P. Hadoulis that should the tailshaft be fitted in any ship the markings on the shaft are such that they would be accepted by the Society without question.

1st March, 1961.

DWOK